

## FLAW DETECTION

### LEAK DETECTOR

952

#### GAS LEAKS

Suitable for the detection of gas leaks: compressed air, oxygen, butane, propane, CO<sub>2</sub> etc. on connectors or valves. Instantly detects leaks by foaming. The aerosol has an adjustable nozzle. Contains a corrosion inhibitor which prevents subsequent metal oxidation.



Cl - F - Br - S:  
< 200 ppm  
PMUC: 07-010

4952A4	650 ml aerosol
6958A4	650 ml aerosol PMUC
2952J1	5 kg jerrycan
295205	60 kg drum

### BLEU DE PRUSSE

975

#### PLANARITY DEFECT

Blue indicator for checking connectors and fittings on flat surfaces. Reveals high and low points on abutment surfaces which can then be machined to make the final adjustments. Cleans off with ORASOLV B30 - 564.



■ blue  
VOC content: 0%  
Non-flammable

1975F9	22 ml tube
1975T3	100 ml tube

### CRACK DETECTOR

957

#### CRACKS, FISSURES – PENETRATING RED DYE

Highly effective red fluid which penetrates the cracks, micro-fissures and pores of metals, whether blocked or not. For testing welds during construction and monitoring wear after several years' use on tanks, pylons (ski resorts, cable cars), machine frames, cars, etc. Clean with 503, apply 957, allow the product to penetrate, wipe off, then apply 956. Flaws appear in red when white indicator 956 is applied. ASME Section V compliant.

■ red  
Capacity: 200 m

4957A4	650 ml aerosol
2957J1	5 l jerrycan

### CRACK DETECTOR

956

#### CRACKS, FISSURES - WHITE INDICATOR

White product which, when applied after the 957 product onto cracks, micro-fissures and porous metal, blocked or otherwise, makes the 957 product which has penetrated into the material reappear, thereby identifying any flaws. For testing welds during construction and monitoring wear after several years' use on tanks, pylons (ski resorts, cable cars), machine frames, automobiles etc. Clean with 503, apply 957, let it penetrate, sweep away, apply 956. Flaws appear in red when white indicator 956 is applied. ASME Section V compliant.

■ white  
Capacity: 150 m

4956A4	650 ml aerosol
--------	----------------

### KLEANER

503

#### CRACKS, FISSURES - DRY SOLVENT

Helps prepare surfaces before detecting cracks and fissures using the 2 products from the CRACK DETECTOR range. Degreasing solvent with ultra quick evaporation that efficiently removes dust and greasy marks that could interfere with the action of detection products. Does not damage plastic, rubber, polymers etc.

Scent: apple  
Flash point:  
< 0°C

4503A4	650 ml aerosol
--------	----------------

